

PRODUCT SAFETY NOTICE

48764 – Titan TTB419STM Wallpaper Stripper

Screwfix have been made aware that in some circumstances a number of products, batch number 16W52, have shown a potential risk of water leaking from the socket at the back of the tank. You can find the batch number on the top of the tank.

Despite rigorous quality control procedures, Screwfix has identified a potential safety issue with this product. Due to the potentially serious nature of the risk and our commitment to safety, we are issuing this safety notice.

The product effected is:

Code	Product Description	Barcode	Model Number
48764	Titan Wallpaper Stripper	05346738	TTB419STM

These products possibly effected are those bought from 23/12/2016.



If you have purchased this product from us, and you notice any water coming from the back of the tank, or concerned your product has this fault please stop using it immediately and follow the steps below.

Please return it to your local **Screwfix Trade Counter** where you will be given a refund to the full value of your purchase. Alternatively, we can arrange collection of the item(s), please contact us on **03330 112 112** for a collection to be arranged and a full refund provided. Alternatively, please visit our website for more information: www.screwfix.com.

If you have purchased this for a customer in the course of your own business, please contact them immediately, advise them to stop using the product and make arrangements for it to be removed.

Thank you in advance for your co-operation in this matter and we apologise for any inconvenience caused.

Screwfix, Trade House, Mead Avenue, Yeovil, Somerset, BA22 8RT

[VERSION]